# 72603/72608/72609

# Metric/English Conversion Instructions

Turn Unit on, press ST button and hold for 6 seconds or until the 4 line display changes to the following;

## SYSTEM MENU

## UNITS

## PRESS CONTINUE TO

## SELECT MENU

Press Continue button to select UNITS Menu. Use scroll arrow to switch from lbs. to kgm (or reverse for English conversion) Press continue button to confirm selection, you will then go back to the display above, press Continue one more time to save changes and go back to normal function

# Calibration Instructions

1. Press & hold ST
2. Press 3 Calibration
3. Press 1 for 800 or 2 for 100 lbs then press continue
4. Press Zero to Zero box out
5. Set weight on Left front pad
6. Press Continue to calibrate
7. Press 2 to advance to next channel
8. Repeat steps 4 – 7 for each channel.

   When last channel is calibrated, Press 2 to advance (Very important as the calibration will not save if this step is missed).  When done correctly, the control box will return to user mode.