



HOW-TO

Load a firmware on a weight indicator


1. Copy the ".EXE" file on the desktop
2. Connect the Indicator to the PC
3. Double click on the executable file:




4. Select the COM port (of the PC) where is connected the indicator. If it's using a USB/Serial converter it's necessary to check the box "USB->COM", Then press OK.
5. It will be displayed the following message:



6. Turn on the indicator in order to start the loading. The following message appears automatically when the indicator is ready to be updated:



7. If the update procedure is completed successfully, it will be displayed the following message:



8. At the end of the updating, turn on the indicator and make a technical default