

TP2100

Thermal Printer

Connect thermal printer to compatible Charder scales and print out measurement data from display panels including weight, height, BMI, tare and pretare weight with one button. Printer is connected to device via USB cable or Wireless transmission (TP2110 only).

Specifications

Overall Dimensions	120(W) x 80(D) x 50(H) mm
	Number of dots: 384 dots/line Resolution: 8/dots/mm
Printing	Paper: 57.5+0.5mm(W)x \varnothing 30mm max Printing speed: 75 mm/s
Device Weight	0.2 kg
Data Transfer	RS232 to USB
Power Supply	12V Power Adapter
Compatible devices	DP2701, DP3400, DP3710, DP4400, DP4600, DP4800D

